THE SEPARATING ROOF WITH ASSOCIATED MECHANISMS

Fig 10



LAPP the 28/04/95